

FIGURE 2

FIGURE 3






FIG 4: Ratings of debris accumulation on 316 Stainless Steel Balls

* Rating per Kodak internal test method based on weight loss. The higher the number the greater the weight loss (debris generated).







FIG. #: Average Volume Loss of Film Cores sliding vs. 316 SS

BEST AVAILABLE COPY





Volume Loss Measurements of Various Cores and Table of calculated Wear Rate Coefficients (k).

FIG. 58 QUALTITATIVE MEASUREMENTS

BEST AVAILABLE COPY

			Coefficient of Friction			•
		Mold Texture (Ra				
SPI Finish	Finish Type	(microns, measured)	(+2 STD)	(-2 STD)	Average	STD
HIPS (Novacor "5104")	600 Grit Paper	0.10	0:63	0.53	0.58	
A1	#3 Diamond Buff	0.02	0.32	0.28	0.30	0.012
A3	#15 Diamond Buff	0.04	0.28	0.24	0.26	0.01
D2E	EDM, Charmilles 18	0.80	0.29	0.23	0.26	0.015
. B1	600 Grit Paper	0.10	0.24	0.18	0.21	0.017
D1	#12 Glass Bead	0.37	0.24	0.18	0.21	0.017
СЗ	320 Stone	0.29	0.25	0.17	0.21	0.021
D2	#10 Glass Bead	0.37	0.26	0.16	0.21	0.025
C1	600 Stone	0.32	0.21	0.17	0.19	0.01
B3	320 Grit Paper	0.23	0.21	0.15	0.18	0.015
D3	EDM, Charmilles 24	1.57	0.2	0.1	0.15	0.026




FIG 6: Static coefficient of friction of photographic film (emulsion side) against AISI type 316 stainless steel vs. mold surface texture

Mechanical Property Comparison

	HIPS	PBT		
	Nova "5104"	GE "Valox 325"		
Tensile Eleongation	55%	200%		
Flexural Strength	62 MPa	83 MPa		
Tensile Strength	27 MPa	52 MPa		
Flexural Modulus	2,300 Mpa	2,300 MPa		

FIG 7: Mechanical property comparison for PBT v HIPS

